

## PHOTOGRAPHIC EVIDENCE

Photo #1: Front View of Parachute Equipment

Photo #2: Back View of Parachute Equipment

Photo #3: Close up of handles and equipment

Photo #4: Close up of personal gear bag attachment & reserve belly-band

Photo #5: Liston accident site

Photo #6: Liston's drogue and reserve parachute bag

Photo #7: Line entanglement at Liston's site

Photo #8: Close up of line entanglement

Photo #9: Liston's main parachute in deployment bag

Photo #10: Liston's reserve parachute in deployment bag

Photo #11: "Lark's Head" knot (Liston site)

Photo #12: Close up of "Lark's Head" knot (Liston site)

Photo #13: Drogue at Liston's site

Photo #14: View of Roach's reserve parachute & landing site

Photo #15: Roach's main parachute deployment bag

Photo #16: Roach's main riser w/upper RSL attached

Photo #17: View of RSL attached by Velcro to Roach's harness

Photo #18: Birch Hill sign



Reserve  
parachute

PG bag  
with cover

Photo 1: Front view of smokejumper gear, including personal gear (PG) bag and cover.




Photo 2: Rear view of smokejumper wearing gear.



Photo 3: Close-up of handles and equipment.




Photo 4: Shows how PG bag (with new cover) is attached to the harness below the reserve parachute.



Photo 5: Liston's accident site.



Photo 6: Liston's drogue reserve parachute deployment bag.



Photo 7: Line entanglement at Liston's site (before it was disturbed by emergency medical procedures).



Photo 8: Close-up of line entanglement (reserve lines wrapped around drogue bridle).



Photo 9: Liston's main parachute still in the deployment bag.



Photo 10: Liston's reserve parachute in deployment bag (suspension lines in foreground were disturbed by emergency medical procedures).



Photo 11: Entanglement of drogue sail and reserve pilot chute bridle at Liston's site. This is referred to as "Lark's Head Knot."




Photo 12: Close-up of entanglement of drogue sail and reserve pilot chute bridle at Liston's site.



Photo 13: Drogue at Liston's site.



Photo 14: View of Roach's reserve parachute and landing site.



Photo 15: Roach's main parachute still in deployment bag.



Photo 16: Roach's main riser with upper reserve static line attached.

